

STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

1315 W. 4th Avenue • Kennewick, Washington 99336-6018 • (509) 735-7581

June 17, 2003

Mr. Keith Klein United States Department of Energy P. O. Box 550, MSIN: A7-50 Richland, Washington 99352

Mr. Keith Thomson Fluor Hanford Incorporated P.O. Box 1000, MSIN: H5-20 Richland, Washington 99352 RECEIVED JUN 1 9 2003

EDMC

Dear Messrs. Klein and Thomson:

Re: Completion of inspection of Hanford Laboratories

On June 3, 2003, the Washington State Department of Ecology (Ecology) conducted a hazardous waste inspection of generator activities at the 222-S and Waste Sampling and Characterization Facility laboratories operated by Fluor Hanford Incorporated (FH) for the United States Department of Energy-Richland Operations Office.

No violations were revealed at the FH facilities inspected, and Ecology considers the inspection closed. If you have any questions regarding this letter, please contact me at (509) 736-3031.

Sincerely,

Bob Wilson

Compliance Specialist

Bob Willow

Nuclear Waste Program

BW:nc

cc: Ed MacAlister, USDOE

Lucinda Borneman, FH

Todd Martin, HAB

Rick Gay, CTUIR

Pat Sobotta, NPT

Russell Jim, YN

Ken Niles, OOE

Administrative Record: 222-S